


Absolute, Gauge, and Vacuum Pressures



$$P_{gage} = P_{abs} - P_{atm} \quad (kPa)$$

$$P_{vac} = P_{atm} - P_{abs} \quad (kPa)$$